

Attachment B. Contributing Elements

Lot 1: The cabin on lot 1 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed, log rafter tails
- Rubble masonry chimney, composed of stone set in concrete
- Unaltered, divided light, wood windows
- Battened gable end treatment
- Historic front porch addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry cellar building with wood shingle roof
- Rubble masonry outdoor stone fireplace

Lot 2: The cabin on lot 2 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Rubble masonry chimney, composed of stone set in concrete
- Unaltered, divided light, wood windows
- Corner boards
- Wood shingled gable end treatment
- Rubble masonry porch walls, composed of stone set in concrete
- Flagstone sidewalk and stairs
- Vertical log siding door with window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Vertical log sided garage with decorative log gable end treatment

Lot 4: The cabin on lot 4 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Saddle notched log corners
- Unaltered, divided light, wood windows
- Wood shingle roof material
- Triple paneled wood door with single pane window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided garage with original roof, windows and door

Lot 5: The cabin on lot 5 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Corner boards
- Exposed rafter tails
- Unaltered, divided light, wood windows including a 15 light wood picture window

- Dove-tailed parge boards
- Vertical log siding gable end treatment
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Wood shingle roof material
- Vertical wood plank door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided generator shed
- Log sided guest cabin/garage with original roof, windows, and doors
- Rubble stone masonry construction including an outdoor stone fireplace and retaining wall

Lot 6: While the cabin on lot 6 of the North Shore Tract is itself not contributing, the lot exhibits several characteristics important to its designation as a historically significant site, which include the following:

- Log sided garage
- Rubble masonry construction including a stone patio and retaining walls

Lot 6+: The cabin on lot 6+ of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed log purlin ends
- Saddle notched log corners
- Two chimneys, one rubble masonry composed of stone set in concrete, one brick
- Rubble masonry foundation composed of stone set in concrete
- Six light, double paneled, wood door
- Unaltered, divided light, wood windows

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry construction including an outdoor stone fireplace and retaining wall

Lot 7: While the cabin on lot 7 of the North Shore Tract is itself not contributing, the lot exhibits several characteristics important to its designation as a historically significant site, which include the following:

- Rubble masonry construction including a stone lamppost, bar-b-q, table, smoker, bench and planter.

Lot 8: The cabin on lot 8 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Corner boards
- Unaltered, divided light, wood windows
- Triple paneled wood door with window
- Historic, shed-roofed rear addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry construction including an outdoor stone fireplace
- Log sided outhouse with original detailing
- Log sided storage shed with original detailing

Lot 11: The cabin 11 on lot of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed, log rafter tails
- Exposed log purlin ends
- Two rubble masonry chimneys, composed of stone set in concrete
- Saddle notched log corners
- Unaltered, divided light, wood windows
- Wood shingle roof material
- Vertical wood plank door with three windows

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry construction including an outdoor stone fireplace
- Wood shingle clad outhouse with original detailing
- Log sided storage shed with original detailing

Lot 12: The cabin on lot 12 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Corner boards
- Horizontal log siding gable end treatment
- Brick chimney
- Unaltered, divided light, wood window
- Triple paneled wood door with window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Wood shingle clad outhouse with original detailing

Lot 17: The cabin on lot 17 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Square notched log corners
- Vertical log siding gable end treatment
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Unaltered, divided light, wood windows
- Triple paneled wood door with window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed garage with original detailing
- Log sided outhouse

Lot 18: Both cabin and outbuildings on lot 18 of the Shoreline Tract have been altered to the point that they no longer exhibit enough historical characteristics to allow their designation as historically significant structures.

Lot 19: Both cabin and outbuildings on lot 19 of the Shoreline Tract have been altered to the point that they no longer exhibit enough historical characteristics to allow their designation as historically significant structures.

Lot 20: Both cabin and outbuildings on lot 20 of the Shoreline Tract have been altered to the point that they no longer exhibit enough historical characteristics to allow their designation as historically significant structures.

Lot 21: The cabin on lot 21 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed rafter tails
- Battened gable end treatment
- Unaltered, divided light, wood windows
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Battened wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided doghouse
- Clapboarded outhouse with original detailing
- Log constructed storage shed with original detailing

Lot 22: The cabin on lot 22 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Corner boards
- Rubble masonry chimney, composed of stone set in concrete
- Horizontal log siding gable end treatment
- Square notched log corners
- Unaltered, divided light, wood windows
- Triple paneled wood door with window
- Historic log sided el addition

Lot 23: While the cabin on lot 23 of the Shoreline Tract is itself not contributing, the site exhibits several characteristics important to its designation as a historically significant site, which include the following:

- Log sided boathouse with original detailing
- Outhouse with original detailing

Lot 24: The cabin on lot 24 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed log purlin ends
- Z-braced, battened wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed garage with some original detailing
- Rubble masonry construction including an outdoor stone fireplace

Lot 25: The cabin on lot 25 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed log purlin ends
- Saddle notched log corners
- Unaltered, divided light, wood windows
- Sill log foundation
- Double paneled wood door with window
- Historic addition with original detailing

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry construction including an outdoor stone fireplace
- Log sided outhouse with original detailing
- Log constructed storage shed with original detailing

Lot 26: The cabin on lot 26 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed log rafter tails
- Two rubble masonry chimneys, composed of stone set in concrete
- Vertical log siding gable end treatment
- Unaltered, divided light, wood windows including an 18 light wood picture window
- Rubble masonry foundation, composed of stone set in concrete
- Battened wood door
- Historic addition with original detailing

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided outhouse with some original detailing

Lot 27: The cabin on lot 27 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed log purlin ends
- Rubble masonry foundation, composed of stone set in concrete
- Z-braced, vertical wood plank door with six light window
- Unaltered, divided light, wood windows

Lot 27a: The cabin on lot 27a of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Board and batten gable end treatment
- Brick masonry chimney
- Vertical log sided door with four light window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided outhouse with original detailing

Lot 28: The cabin on lot 28 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed log purlin ends
- Rubble masonry chimney, composed of stone set in concrete
- Vertical wood plank door with window
- Small, historic, log-sided bathroom addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided guesthouse/garage with original detailing
- Log-sided spring box with original detailing
- Log-sided storage shed with original detailing

Lot 29: The cabin on lot of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

Further contributions to the eligibility of the lot are made by the subsequent improvements:

Lot 30: The cabin on lot 30 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Sill log foundation
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Exposed log purlin ends
- Saddle notched log corners
- X-braced wood door with a nine light window
- Wood shingle roof material
- Historic, log-sided kitchen addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed guest cabin with original detailing
- Log-sided storage shed/restroom with original detailing

Lot 31: The cabin on lot 31 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Sill log foundation
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Saddle notched log corners
- Vertical wood plank door
- Historic addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided boathouse with some original detailing
- Log-sided generator with some original detailing
- Log constructed guest cabin with some original detailing

Lot 32: The cabin on lot 32 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Saddle notched log corners
- Unaltered, divided light, wood windows
- Sill log foundation
- Six paneled wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided outhouse with original detailing

Lot 48: The cabin on lot 48 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed log purlin ends
- Rubble masonry chimney, composed of stone set in concrete
- Unaltered, divided light, wood windows
- Vertical plank, wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Wood cooler/bathroom with some original detailing
- Rubble masonry construction including an outdoor stone fireplace

Lot 50: The cabin on lot 50 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails

Lot 51: The cabin on lot 51 of the North Shore Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Unaltered, divided light, wood windows
- Exposed rafter tails
- Triple paneled wood door with window
- Historic addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Wood shingle sided outhouse with original detailing

Lot 52: Both cabin and outbuildings on lot 52 of the Shoreline Tract have been altered to the point that they no longer exhibit enough historical characteristics to allow their designation as historically significant structures.

Lot 53: The cabin on lot 53 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Unaltered, divided light, wood windows
- Board and batten gable end treatment
- Exposed rafter tails
- Corner boards
- Two chimneys, one brick masonry, one composed of concrete block
- Single paneled wood door with window

Lot 54: The cabin on lot 54 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Two rubble masonry chimneys, composed of stone set in concrete
- Saddle notched log corners
- Exposed rafter tails
- Ten light, divided glass, wood door
- Some unaltered, divided light, wood windows

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided outhouse with original detailing

Lot 55: The cabin on lot 55 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Board and batten gable end treatment
- Exposed rafter tails
- Screened kitchen window box
- Some unaltered, divided light, wood windows
- Vertical, log sided door
- Wood shingle roof material

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided outhouse with original detailing

Lot 56: The cabin on lot 56 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Board and batten gable end treatment
- Masonry brick chimney
- Exposed rafter tails
- Screened kitchen window box
- Wood shingle roof material
- Unaltered, divided light, wood window
- Vertical, log sided door with single light window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Wood shingle sided outhouse with original detailing

Lot 57: The cabin on lot 57 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Wood box
- Unaltered, divided light, wood windows
- Triple paneled wood door with window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Shiplap sided outhouse with original detailing

Lot 58: The cabin on lot 58 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Rubble masonry chimney, composed of stone set in concrete
- Corner boards
- Exposed rafter tails
- Some unaltered, divided light, wood windows

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log sided outhouse with original detailing
- Log sided storage shed with original detailing

Lot 59: The cabin on lot 59 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Rubble masonry foundation, composed of stone set in concrete
- One rubble masonry chimney, composed of stone set in concrete
- Saddle notched log corners
- Unaltered, divided light, wood windows
- Horizontal, log-sided wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log outhouse with some original detailing

Lot 60: The cabin on lot 60 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed log purlin ends
- Saddle notched log corners with flared crowns
- Rubble masonry chimney, composed of stone set in concrete
- Z-braced, vertical wood plank door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry cellar, composed of stone set in concrete
- Wood shingle sided outhouse with original detailing

Lot 61: The cabin on lot 61 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed log rafter tails
- Saddle notched log corners
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick complete with vertical log on which the chimney stack rests

- Vertical log siding gable end treatment
- Z-braced vertical plank wood door
- Unaltered, divided light, wood windows

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed outhouse with original detailing
- Rubble stone masonry construction including a stone patio

Lot 62: The cabin on lot 62 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Battened gable end treatment
- Saddle notched log corners
- Rubble masonry chimney, composed of stone set in concrete
- Rubble masonry foundation, composed of stone set in concrete

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Rubble masonry cellar, composed of stone set in concrete
- Log constructed outhouse with some original detailing

Lot 63: The cabin on lot 63 of the Shoreline Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed rafter tails
- Vertical log siding gable end treatment
- Rubble masonry foundation, composed of stone set in concrete
- Unaltered, divided light, wood windows
- Triple paneled wood door with four light window
- Wood shingle roof material

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided outhouse with original detailing

Lot 67: The cabin on lot 67 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Unaltered, divided light, wood windows
- Clapboard gable end treatment
- Saddle notched log corners
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Battened wood door

Lot 68: The cabin on lot 68 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Two chimneys, one brick masonry, one concrete block

- Battened gable end treatment
- Some unaltered, divided light, wood windows including two 15 light picture windows
- Vertical log-sided wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Clapboard sided garage with some original detailing
- Log-sided outhouse with some original detailing

Lot 69: The cabin on lot 69 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Vertical log siding gable end treatment
- Metal ridge cap
- Saddle notched log corners
- Wood shingle roof material
- Vertical log siding wood door
- Unaltered, divided light, wood windows
- Historic bathroom addition

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided boathouse with original detailing
- Log-sided garage/sleeping quarters with original detailing
- Poured concrete construction including an outdoor fireplace
- Log constructed outhouse with original detailing

Lot 70: The cabin on lot 70 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Unusual design with two wings forming a wide V connected by a breezeway
- Vertical wood plank door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Faced stone construction including an outdoor stone fireplace built into the cabin's façade and rubble masonry retaining wall surrounding a concrete patio

Lot 71: The cabin on lot 71 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Boxed eaves
- Brick masonry chimney
- Unaltered, divided light, wood windows including a 24 light picture window
- Triple paneled wood door with four light window
- Wood shingle roof material

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Clapboarded outhouse with original detailing

Lot 72: The cabin on lot 72 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Two rubble masonry chimneys, composed of stone set in concrete
- Exposed rafter tails
- Saddle notched log corners
- Vertical wood plank door
- Wood shingle roof material

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed garage with original detailing
- Log constructed gazebo with original detailing

Lot 73: Both cabin and outbuildings on lot 73 of the Shoreline Tract have been altered to the point that they no longer exhibit enough historical characteristics to allow their designation as historically significant structures.

Lot 74: The cabin on lot 74 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Exposed rafter tails
- Unaltered, divided light, wood windows including a 35 light picture window
- X-braced, vertical plank wood door
- Two chimneys, one rubble masonry, composed of stone set in concrete, one brick
- Wood shingle roof material

Lot 75: The cabin on lot 75 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Unaltered, divided light, wood windows, including an 18 light picture window
- Exposed rafter tails
- Two brick masonry chimneys
- Battened gable end treatment
- Wood shingle roof material
- Vertical wood plank door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided boathouse with original detailing
- Outhouse with some original detailing

Lot 76: The cabin on lot 76 of the Kinney Point Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Two brick masonry chimneys

- Exposed rafter tails
- Some unaltered, divided light, wood windows

Paradise Valley Lot 1: The cabin on lot 1 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Boxed eaves
- Some unaltered, divided light, wood windows
- Parge boards
- Brick masonry chimney
- Single paneled wood door with nine lights

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided garage with some original detailing

Paradise Valley Lot 2: The cabin on lot 2 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Saddle notched log corners
- Some unaltered, divided light, wood windows
- Exposed rafter tails
- Vertical, log-sided, wood door with window

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Clapboard sided outhouse with original detailing

Paradise Valley Lot 3: The cabin on lot 3 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Exposed rafter tails
- Corner boards
- Decorative parge boards which widen at the end
- Brick masonry chimney
- Some unaltered, divided light, wood windows
- Vertical, log-sided, wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided outhouse with original detailing
- Log woodshed with original detailing

Paradise Valley Lot 4: The cabin on lot 4 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Square notched hewn logs

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log constructed storage/outhouse with some original detailing

Paradise Valley Lot 6: The cabin on lot 6 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Corner boards

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Light framed outhouse with some original detailing

Paradise Valley Lot 7: The cabin on lot 7 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Square notched hewn logs
- Brick masonry chimney
- Battened gable end treatment
- Some unaltered, divided light, wood windows including a 16 light picture window
- Battened wood door with decorative iron straps

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Log-sided outhouse with original detailing

Paradise Valley Lot 8: The cabin on lot 8 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Unaltered, divided light, wood windows including a nine light picture window
- Exposed rafter tails
- Brick masonry chimney
- Square notched hewn logs
- Battened wood door

Paradise Valley Lot 9: The cabin on lot 9 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Light frame structural system with Shevlin log siding
- Unaltered, divided light, wood windows and a 30 light metal picture window
- Diagonally battened gable end treatment
- Exposed rafter tails

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Board and battened outhouse with original detailing

Paradise Valley Lot 10: The cabin on lot 10 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Unaltered, divided light, wood windows and a 30 light metal picture window
- Saddle notched log corners with flared crowns

- Battened gable end treatment
- Exposed rafter tails
- Vertical, log-sided, wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Light framed outhouse with original detailing
- Light framed storage shed with original detailing

Paradise Valley Lot 11: The cabin on lot 11 of the Paradise Valley Tract exhibits several characteristics important to its designation as a historically significant structure, which include the following:

- Log construction
- Exposed rafter tails
- Exterior stair leading to the second floor door
- Square notched hewn logs
- Unaltered, divided light, wood windows
- Double X-braced wood door

Further contributions to the eligibility of the lot are made by the subsequent improvements:

- Two shingle sided outhouse with original detailing
- Log-sided storage shed with original detailing

Attachment C.

Primary Façades of Recreation Residences in the Warm Lake Basin

A Listing Prepared For Recreation Residence Management
in the Warm Lake Basin

Primary Façade is that view of the recreation residence which provides the most important architectural presentation of the structure. Sometimes called the principle elevation, it can be the most decorated facade, the facade providing the most living activity, or the best view of the structure. It can be, but is not necessarily, the entry to the building. If the structure has no clear primary architectural focus, the Primary Facade is the view that is the most visible from a public perspective.

Warm Lake Residence Primary Façades

Lot 1: The North façade, which faces Warm Lake Lodge and is distinguished by being the location of the primary entrance to the structure enclosed within a screened sleeping porch.

Lot 2: The Southeast façade, which faces the Warm Lake Campground and is distinguished by rubble stone masonry flanking the primary entrance to the structure as well as the rubble masonry chimney.

Lot 4: The South façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure

Lot 5: The South façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 6: The South façade, which faces Warm Lake and is distinguished by being the location of multiple picture windows as well as a large shed dormer that emphasize the importance of the Lake.

Lot 6+: The East façade, which faces lot 6 and 7 and is distinguished by being the location of the primary entrance to the structure.

Lot 7: The East façade, which faces lot 6 and is distinguished by being the location of the primary entrance to the structure.

Lot 8: The South façade, which faces lot 6+ and is distinguished by being the location of the primary entrance to the structure.

Lot 11: The East façade, which faces lot 51 and is distinguished by being the location of the primary entrance to the structure.

Lot 12: The East façade, which faces lot 11 and is distinguished by being the location of the primary entrance to the structure.

Lot 17: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure enclosed within a screened sleeping porch.

Lot 18: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 19: The façade, which faces Warm Lake and is distinguished by being the location of the large, cathedral-windowed gable that emphasizes the importance of the lake.

Lot 20: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 21: The South façade, which faces lot 22 and is distinguished by being the location of the primary entrance to the structure as well as the rubble masonry chimney.

Lot 22: The West façade, which faces the Shoreline Drive Road and is distinguished by being the location of the primary entrance to the structure.

Lot 23: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the deck.

Lot 24: The South façade, which faces lot 25 and is distinguished by being the location of the primary entrance to the structure.

Lot 25: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the screened sleeping porch.

Lot 26: The West façade, which faces Shoreline Drive Road and is distinguished by being the location of the primary entrance to the structure.

Lot 27: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 27a: The West façade, which faces Shoreline Drive Road and is distinguished by being the location of the primary entrance to the structure.

Lot 28: The Southwest façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure as well as the rubble stone masonry chimney.

Lot 29: The Southeast façade, which faces lot 30 and is distinguished by being the location of the primary entrance to the structure.

Lot 30: The West façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure as well as the rubble stone masonry chimney.

Lot 31: The North façade, which faces lot 30 and is distinguished by being the location of the primary entrance to the structure as well as the principle deck.

Lot 32: The West façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure.

Lot 48: The Northwest façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the residence's deck.

Lot 50: The South façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 51: The South façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the principle deck.

Lot 52: The South façade, which faces lot 53 and is distinguished by being the location of the primary entrance to the structure as well as the residence's deck.

Lot 53: The North façade, which faces lot 52 and is distinguished by being the location of the primary entrance to the structure.

Lot 54: The South façade, which faces lot 55 and is distinguished by being the location of the primary entrance to the structure as well as one of the chimneys.

Lot 55: The West façade, which faces Shoreline Drive and is distinguished by being the location of the primary entrance to the structure as well as the concrete block chimney.

Lot 56: The West façade, which faces Shoreline Drive and is distinguished by being the location of the primary entrance to the structure.

Lot 57: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the residence's deck.

Lot 58: The West façade, which faces Shoreline Drive and is distinguished by being the location of the primary entrance to the structure.

Lot 59: The North façade, which faces lot 58 and is distinguished by being the location of the primary entrance to the structure as well as the rubble masonry chimney.

Lot 60: The South façade, which faces lot 61 and is distinguished by being the location of the primary entrance to the structure.

Lot 61: The South façade, which faces lot 62 and is distinguished by being the location of the primary entrance to the structure as well as a brick chimney.

Lot 62: The South façade, which faces lot 63 and Shoreline Drive and is distinguished by being the location of the primary entrance to the structure as well as the shed-roofed porch.

Lot 63: The North façade, which faces lot 27a and is distinguished by being the location of the primary entrance to the structure.

Lot 67: The Southeast façade, which faces lot 68 and is distinguished by being the location of the primary entrance to the structure as well as one of the rubble masonry chimneys.

Lot 68: The Southwest façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure.

Lot 69: The South façade, which faces lot 70 and is distinguished by being the location of the primary entrance to the structure as well as a historic bathroom addition.

Lot 70: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as the faux stone chimney and concrete patio.

Lot 71: The West façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure.

Lot 72: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure.

Lot 73: The Southwest façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure as well as the significant porch addition.

Lot 74: The Southwest façade, which faces Kinney Point Road and is distinguished by being the location of the primary entrance to the structure.

Lot 75: The South façade, which faces lot 76 and is distinguished by being the location of the primary entrance to the structure as well as a full length entry porch.

Lot 76: The East façade, which faces Warm Lake and is distinguished by being the location of the primary entrance to the structure as well as a significant deck.

Paradise Valley Residence Primary Façades

Lot 1: The Southeast façade, which faces Paradise Valley and is distinguished by being the location of the primary entrance to the structure.

Lot 2: The East façade, which faces lot 1 and is distinguished by being the location of the primary entrance to the structure.

Lot 3: The Northeast façade, which faces Paradise Valley Road and lot 7 and is distinguished by being the location of the primary entrance to the structure.

Lot 4: The East façade, which faces lot 3 and is distinguished by being the location of the primary entrance to the structure.

Lot 6: The Northeast façade, which faces Paradise Valley Road and lot 7 and is distinguished by being the location of the primary entrance to the structure.

Lot 7: The Southwest façade, which faces Paradise Valley Road and lot 3 and is distinguished by being the location of the primary entrance to the structure.

Lot 8: The East façade, which faces lot 9 and is distinguished by being the location of the primary entrance to the structure.

Lot 9: The South façade, which faces Paradise Valley Road and lot 1 and is distinguished by being the location of the primary entrance to the structure.

Lot 10: The Southwest façade, which faces Paradise Valley Road and is distinguished by being the location of the primary entrance to the structure.

Lot 11: The South façade, which faces Paradise Valley and is distinguished by being the location of the primary entrance to the structure as well as an exterior stairway to the second floor.